



Christopher M. Brock
Direct Dial: 248.641.1208
brock@hdp.com

July 30, 2004

Director for Patents
P.O. Box 1450
Alexandria, Virginia 22313-1450

**Certificate
AUG 06 2004
of Correction**

Re: Patent No. 6,720,689 B2
Issued: April 13, 2004
Inventors: Michael J. Agnes et al
For: Brushless Motor Having Capacitors Mounted On Sidewall Of
Motor Housing
Atty. Docket: 0275L-000527/CPA

Sir:

We have reviewed the above-identified patent and have found the following errors which appear to require a Certificate of Correction:

Column 11, line 45, (Claim 14),
(Amendment dated January 16, 2003, page 3, Claim 14, line 6),
"POB" should be -- PCB --.

Column 12, line 63, (Claim 28),
(Amendment dated September 22, 2003, page 9, Claim 29, line 2),
after "pair" insert - - of - - .

Column 14, line 8, (Claim 36),
(Amendment dated September 22, 2003, page 10, Claim 37, line 8),
after "brushless" insert - - motor - - .

CERTIFICATE OF MAILING/ TRANSMISSION

I hereby certify that this correspondence is being deposited with the United States Postal Service as express mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, or facsimile transmitted to the U.S. Patent and Trademark Office on the date indicated below.

Date: July 30, 2004

Express Mail Label No. EV 533 146 639 US (7/30/2004)

Typed Name: Christopher M. Brock

Signature:

P.O. Box 828
Bloomfield Hills, MI 48303 U.S.A.

FOR COURIER DELIVERY ONLY
5445 Corporate Drive
Troy, Michigan 48098
248.641.1600

CABLE
Patents Troy, Michigan
Telex No. & Reply
287637 Harness UR
Telefacsimile 248.641.0270

Metropolitan
Detroit, MI St. Louis, MO Washington, D.C.

www.hdp.com

EV 533 146 639 US

Director for Patents
July 30, 2004
Page 2


Re: Patent No. 6,720,689 B2
Issued: April 13, 2004

Column 14, line 26, (Claim 37),
(Amendment dated September 22, 2003, page 11, Claim 38, line 9),
"packet" should be -- pocket --.

Enclosed herewith is an original and copy of the Patent and Trademark Office Certificate of Correction form which we request be approved for the above-identified patent.

The Director is hereby authorized to charge any fees which may be required to Account No. 02-2548. A duplicate copy of this sheet is enclosed.

Respectfully submitted,

By 
Christopher M. Brock
Reg. No. 27313

CMB/jb
Encls.

HARNESSEY



Christopher M. Brock
Direct Dial: 248.641.1208
brock@hdp.com

July 30, 2004

Director for Patents
P.O. Box 1450
Alexandria, Virginia 22313-1450

Re: Patent No. 6,720,689 B2
Issued: April 13, 2004
Inventors: Michael J. Agnes et al
For: Brushless Motor Having Capacitors Mounted On Sidewall Of
Motor Housing
Atty. Docket: 0275L-000527/CPA

Sir:

We have reviewed the above-identified patent and have found the following errors which appear to require a Certificate of Correction:

Column 11, line 45, (Claim 14),
(Amendment dated January 16, 2003, page 3, Claim 14, line 6),
"POB" should be -- PCB --.

Column 12, line 63, (Claim 28),
(Amendment dated September 22, 2003, page 9, Claim 29, line 2),
after "pair" insert - - of - - .

Column 14, line 8, (Claim 36),
(Amendment dated September 22, 2003, page 10, Claim 37, line 8),
after "brushless" insert - - motor - - .

CERTIFICATE OF MAILING/ TRANSMISSION

I hereby certify that this correspondence is being deposited with the United States Postal Service as express mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, or facsimile transmitted to the U.S. Patent and Trademark Office on the date indicated below.

Date: July 30, 2004

Express Mail Label No. EV 533 146 639 US (7/30/2004)

Typed Name: Christopher M. Brock

Signature: 

P.O. Box 828
Bloomfield Hills, MI 48303 U.S.A.

FOR COURIER DELIVERY ONLY
5445 Corporate Drive
Troy, Michigan 48098
248.641.1600

Metropolitan
Detroit, MI St. Louis, MO Washington, D.C.

CABLE
Patents Troy, Michigan
Telex No. & Reply
287637 Harness UR
Telefacsimile 248.641.0270

www.hdp.com

10 AUG 2004

Director for Patents
July 30, 2004
Page 2


Re: Patent No. 6,720,689 B2
Issued: April 13, 2004

Column 14, line 26, (Claim 37),
(Amendment dated September 22, 2003, page 11, Claim 38, line 9),
"packet" should be -- pocket --.

Enclosed herewith is an original and copy of the Patent and Trademark Office Certificate of Correction form which we request be approved for the above-identified patent.

The Director is hereby authorized to charge any fees which may be required to Account No. 02-2548. A duplicate copy of this sheet is enclosed.

Respectfully submitted,

By 
Christopher M. Brock
Reg. No. 27313

CMB/jb
Encls.

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,720,689 B2

Page 1 of 1

DATED : April 13, 2004

INVENTOR(S) : Michael J. Agnes et al

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 11,

Line 45, "POB" should be -- PCB --.

Column 12,

Line 63, after "pair" insert -- of --.

Column 14,

Line 8, after "brushless" insert -- motor --.

Line 26, "packet" should be -- pocket --.

MAILING ADDRESS OF SENDER: Christopher M. Brock
Harness, Dickey & Pierce, P.L.C.
P.O. Box 828
Bloomfield Hills, MI 48303

PATENT NO. 6,720,689 B2

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

10 AUG 2004

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,720,689 B2

Page 1 of 1

DATED : April 13, 2004

INVENTOR(S) : Michael J. Agnes et al

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 11,

Line 45, "POB" should be -- PCB --.

Column 12,

Line 63, after "pair" insert -- of --.

Column 14,

Line 8, after "brushless" insert -- motor --.

Line 26, "packet" should be -- pocket --.

MAILING ADDRESS OF SENDER: Christopher M. Brock
Harness, Dickey & Pierce, P.L.C.
P.O. Box 828
Bloomfield Hills, MI 48303

PATENT NO. 6,720,689 B2

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

10 AUG 2004